

Product model: SCT1200

2 - 1

Important Instruction

Assembly Tools (Available in package)


Socket Head Wrench

Number of people needed to assemble: 2


Time needed to assemble: 15 mins




Package Contents



A *1



B *2



C *1



K *6

Table Quick Start Guide

Product model: SCT1200

2 - 2

Assembly Process

